



2 Holes  $\varnothing 5.5$  to suit  
coach screws at CC 31

Cable entry hole  $\varnothing 10$



2Nos. of SQ. head  
coach screw



2Nos. of rawl plug